

NJS 000 001 170

U S EPA Region 2  
Sites Notification  
New York, NY 10007

Power Systems Division  
McGraw-Edison Company  
Post Office Box 28  
Bloomfield, NJ 07003

201 751 3700  
Telex 139168

June 15, 1981

Gentlemen:

Enclosed is completed EPA Form 8900-1, Notification of Hazardous Waste Site. Which we are submitting per your request. If there are any questions concerning the form, please do not hesitate in contacting the writer at the above address.

Thank you,

*R. Zuccalmaglio*

Randall Zuccalmaglio  
Mgr. Manufacturing Services

RZ/ck

enc.

cc: Mr. R. F. Knudson  
Mr. M. A. Detweiler  
Mr. W. G. Limpert



# EPA Notification of Hazardous Waste Site

United States  
Environmental Protection  
Agency  
Washington DC 20460

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9, 1981.

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

*A10616*

*NJS 00001170*

## A Person Required to Notify:

Enter the name and address of the person or organization required to notify.

Name McGRAW-EDISON CO.  
Street 75 Belmont Ave.  
City Belleville State NJ Zip Code 07109

## B Site Location:

Enter the common name (if known) and actual location of the site.

Name of Site McGRAW-EDISON CO., BATTERY PLANT  
Street Rear of plant site - see enclosed dwg.  
City Bloomfield County Essex State NJ Zip Code 07003

*NJD 096869540*

## C Person to Contact:

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.

Name (Last, First and Title) Mr. W. G. Limpert, Plant Manager  
Phone (201) 751-3700

## D Dates of Waste Handling:

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From (Year) 1972 To (Year) 1981 - Present

## E Waste Type: Choose the option you prefer to complete

Option 1: Select general waste types and source categories. If you do not know the general waste types or sources, you are encouraged to describe the site in Item I—Description of Site.

General Type of Waste:  
Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.

1. ☐ Organics
2. ☒ Inorganics
3. ☐ Solvents
4. ☐ Pesticides
5. ☒ Heavy metals
6. ☒ Acids
7. ☒ Bases
8. ☐ PCBs
9. ☐ Mixed Municipal Waste
10. ☐ Unknown
11. ☐ Other (Specify)

Source of Waste:  
Place an X in the appropriate boxes.

1. ☐ Mining
2. ☐ Construction
3. ☐ Textiles
4. ☐ Fertilizer
5. ☐ Paper/Printing
6. ☐ Leather Tanning
7. ☐ Iron/Steel Foundry
8. ☐ Chemical, General
9. ☐ Plating/Polishing
10. ☐ Military/Ammunition
11. ☐ Electrical Conductors
12. ☐ Transformers
13. ☐ Utility Companies
14. ☐ Sanitary/Refuse
15. ☐ Photofinish
16. ☐ Lab Hospital
17. ☐ Unknown
18. ☒ Other (Specify)

*(Battery Mfg.)*

Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).

### Specific Type of Waste:

EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located.




## Notification of Hazardous Waste Site

## Side Two

## F Waste Quantity

Place an X in the appropriate boxes to indicate the facility types found at the site.

In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.

In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

## Facility Type

1. ☐ Piles
2. ☐ Land Treatment
3. ☐ Landfill
4. ☐ Tanks
5. ☐ Impoundment
6. ☐ Underground Injection
7. ☐ Drums, Above Ground
8. ☐ Drums, Below Ground
9. ☒ Other (Specify) (Settling Pit)

## Total Facility Waste Amount

cubic feet 4805 C

gallons

## Total Facility Area

square feet 1922 S

acres

## G Known, Suspected or Likely Releases to the Environment:

Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☐ Known ☐ Suspected ☐ Likely ☒ None

Note: Items Hand I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

## H Sketch Map of Site Location: (Optional)

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.

SEE ENCLOSED DWG.

## I Description of Site: (Optional)

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

## J Signature and Title:

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify check "Other".

Name Mr. William G. LimpertStreet P.O. Box 28City Bloomfield State NJ Zip Code 07003Signature William G. Limpert Date June 15, 1981 ☒ Owner, Present ☐ Owner, Past ☐ Transporter ☒ Operator, Present ☐ Operator, Past ☒ Other N/A Plant Manager